

ATTACHMENT 2 - PROPOSED ROAD SAFETY IMPROVEMENTS PRIORITY LISTING

Road Safety Audit	Outstanding Recommendation	Priority Order
Pine Mountain Road, Muirlea / Pine Mountain	Installation of guardrail at several locations	1
	Road widening and sealing shoulders at various locations on Pine Mountain Road	2
Alice Street, Goodna	All recommendations listed in the road safety audit except the signalisation of Alice Street / Church Street intersection. Works include but not limited to signs and lines, guardrail upgrades, removal of roadside hazards etc.	3
Bergins Hill Road / Barclay Street / Naomai Street / Charlotte Street, Bundamba	All recommendations listed in the road safety audit are to be addressed. Works include but not limited to signs and lines, guardrail upgrades, street lighting, removal of roadside hazards etc.	4
Lobb Street, Churchill	All recommendations listed in the road safety audit are to be addressed. Works include but not limited to signs and lines, pavement works, footpath works, guardrail upgrades, removal of roadside hazards etc.	5